


# Installation Instructions

For Strut Rod bushing Set # 4-7119



1131 VIA CALLEJON, SAN CLEMENTE, CA 92673


7082  
1.187" O.A.L.



7082  
1.187" O.A.L.

7081  
1.080" O.A.L.

7080  
1.414" O.A.L.



Supplied cup washer  
15.03.43.39

It is recommended that a factory service manual be purchased prior to performing any work on your car or truck.

© 2002 Energy Suspension. All rights reserved.  
May not be reproduced, in any form, or by any means, without the written consent of Energy Suspension.

17097

Updated 14/FEB/02 BRH

# Installation Instructions

For Strut Rod bushing Set # 4-7119



1131 VIA CALLEJON, SAN CLEMENTE, CA 92673


7082  
1.187" O.A.L.



7082  
1.187" O.A.L.

7081  
1.080" O.A.L.

7080  
1.414" O.A.L.



Supplied cup washer  
15.03.43.39

It is recommended that a factory service manual be purchased prior to performing any work on your car or truck.

© 2002 Energy Suspension. All rights reserved.  
May not be reproduced, in any form, or by any means, without the written consent of Energy Suspension.

17097

Updated 14/FEB/02 BRH

# Installation Instructions

For Strut Rod bushing Set # 4-7119



1131 VIA CALLEJON, SAN CLEMENTE, CA 92673


7082  
1.187" O.A.L.



7082  
1.187" O.A.L.

7081  
1.080" O.A.L.

7080  
1.414" O.A.L.



Supplied cup washer  
15.03.43.39

It is recommended that a factory service manual be purchased prior to performing any work on your car or truck.

© 2002 Energy Suspension. All rights reserved.  
May not be reproduced, in any form, or by any means, without the written consent of Energy Suspension.

17097

Updated 14/FEB/02 BRH